07/27/2005 17:08 FAX

RECEIVED CENTRAL FAX CENTER **2** 001/002

Patent

JUL 27 2005

Customer No.: 31561 Docket No. 11809-US-PA

Application No.: 10/707,707

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s):

Lee et al.

Patent No.:

6,881,619 B1

Issue Date:

For

2005/4/19

METHOD FOR FABRICATING A NON-VOLATILE MEMORY AND METAL INTERCONNECT PROCESS

REQUEST FOR CERTIFICATE OF CORRECTION

<u>UNDER 35 U.S.C. §255</u> 002-1-571-273-8300 (Via fax: 1+1 pages)

Certificate
AUG 0 5 2005

Of Correction

Attn: Certificate of Correction Branch United States Patent and Trademark Office Customer Service Window Randolph Building 401 Dulany Street Alexandria, VA 22314

RECEIVED **OIPE/IAP**

AUG 0 2 2005

Dear Sir,

We hereby respectfully file a Request for Certificate of Correction under 35 U.S.C The mistake appears in the patent is of a typographical nature and occurs in good faith. Moreover, the correction does not involve such changes in the patent as would constitute new matter or would require re-examination.

Please charge the fee in the amount of \$100.00 for providing a Certificate of Correction to Account No. 50-2620 under 37 CFR 1.20(a).

Thank you for your assistance in the subject matter. Should you have any inquiries, please do not hesitate to contact me.

> Respectfully Submitted, JIANQ CHYUN Intellectual Property Office

Registration No.: 46,863

Please send future correspondence to:

7F. -1, No. 100, Roosevelt Rd.,

Sec. 2, Taipei 100, Taiwan, R.O.C.

Tel: 886-2-2369 2800

Fax: 886-2-2369 7233 / 886-2-2369 7234

E-MAIL: BELINDA@JCIPGroup.com.tw; USA@JCIPGroup.com.tw

08/02/2005 ZJUHAR1 00000030 502620

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

5 PATENT NO.

: 6,881,619

Page 1 of 1

DATED

: April 19, 2005

INVENTOR(S)

: Lee et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

column 6, lines 3-4, change "370W and 410W, preferably 390W" to --80W and 120W--; and column 7, line 41, change "370W and 410W, preferably 390W" to --80W and 120W--.

The mistake is of a typographical error. The corrections are supported by original claims 11 and 18 about the operation condition for silicon oxide.